



Fig. 1a (PRIOR ART)




Fig. 1b (PRIOR ART)




Fig. 1c (PRIOR ART)




Fig. 2a




Fig. 2c




Fig. 2b




Fig. 3

PRINTER	PRIMARY	NOTES	SECONDARY
A	USE FOR B&W PRINT JOBS OF MORE THAN 20 PAGES	FAST, RELIABLE PRINTER	PPM = 20 STAPLES, COLLATES
B	USE FOR B&W PRINT JOBS OF LESS THAN 20 PAGES, USE FOR EMAIL	SMALL PAPER TRAY, SMALL BUFFER	PPM = 24
⋮			
n	USE FOR EMAIL, B&W PRINT JOBS OF LESS THAN 20 PAGES, SIMPLE COLOR JOBS	PRONE TO JAMMING, INK CARTRIDGES ARE EXPENSIVE	PPM = 24 (BW) 12 (COLOR)

Fig. 4




Fig. 5




Fig. 6




Fig. 7




Fig. 8




Fig. 9




Fig. 10

